

ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Jenny Boliek	2. Log Date: 05/29/03	3. CCR #: 03-0391	4. Rev:	5. Tel: 301-925-1122	6. Rm #: 2058	7. Dept. SE
8. CCR Title: TE_6A.07_PLS.01						
9. Originator Signature/Date Jenny Boliek /s/ 05/29/03			10. Class II	11. Type: CCR	12. Need Date: 29May03	
13. Office Manager Signature/Date Carolyn Whitaker /s/ 05/29/03			14. Category of Change: Other		15. Priority: (If "Emergency" fill in Block 27). Emergency	
16. Documentation/Drawings Impacted (Review and submit checklist):			17. Schedule Impact:		18. CI(s) Affected:OMS	
19. Release Affected by this Change: 6A		20. Date due to Customer: 29May03		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other: NCR ECSed37459						
23. Problem: (use additional Sheets if necessary) The EcPIPRGenerator is very slow (performance is unacceptable.)						
24. Proposed Solution: (use additional sheets if necessary) Deliver TE_6A.07_PLS.01 which will contain a new EcPIPRGenerator with performance enhancements.						
25. Alternate Solution: (use additional sheets if necessary) Wait until next scheduled delivery of PDPS.						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) The problems referenced in section 23 will continue as there is no work around available.						
27. Justification for Emergency (If Block 15 is "Emergency"): After completion of the work for NCR 37459 there was such a big difference in performance Landover is recommending both EDC and LARC install this new binary. There is minimal risk and much added performance.						
28. Site(s) Affected: <input checked="" type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Evelyn Nakamura /s/ 05/29/03			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): Debra Stepp /s/ 05/29/03			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: **Rev:** **Originator:** Jenny Boliek

Telephone: 301-925-1122 **Office:** 2058

Title of Change: TE_6A.07_PLS.01

CSG please make the following tar file from the 6A07EBF1 baseline:

Please make a SOL8 (sun5.8) tar file with the following file:

/ecs/formal/PDPS/PLS/bin/sun5.8/EcPIPRGenerator

Please label this tarfile TE_6A.07_PLS.01

This TE delivers the following NCR:

ECSed37459 OPS_PLS 2 R EDF PLS: PRGenerator is taking too long to validate its inputs.

Note this TE has a significant performance increase and both EDC and LARC are encouraged to install this TE.

PATCH DEPENDENCIES:

This TE can be installed on top of Patch_6A.07_PDPS.02 or any previous 6A.07 version of the EcPIPRGenerator

INSTALLATION INSTRUCTIONS:

PRE-INSTALLATION:

Untar the SOL8 tar file in a <staging_area>/SOL8 directory using the tar command.

```
cd <staging_area>/SOL8/
```

```
chmod 755 EcPIPRGenerator
```

If the EcPIPRGenerator is running stop it.

INSTALLATION:

Log on to the e0pls03 host at EDC or the l0pls02 and l0sps03 hosts at LARC

(p2pls01 in the PVC or t1pls02 in the VATC)

```
cd /usr/ecs/<MODE>/CUSTOM/bin/PLS
```

```
cp <staging_area>/SOL8/EcPIPRGenerator .
```

POST-INSTALLATION:

Re-start the EcPIPRGenerator